| • | Approved For Release 2009/09/16 : CIA-RDP89B00708R000500010024-8 | | |
|--|--|---|---------------|
| | - | SAPC | 1456/ |
| • | | СОРУ | 1072 |
| | | | |
| | | | |
| | | | |
| | | | |
| | March 29, 1957 | | |
| | | · | |
| | • | | |
| | | | |
| | GK: | | |
| | As assistance to us in maintai | ning our monain and malformati | |
| | As assistance to us in maintaining our repair and malfunction records I would appreciate the transmission of the following TWX: | | |
| | · | | 25X1 |
| | TO: | | |
| | FROM: Perkin-Elmer | | |
| | 71770 V 1 | | |
| <i>C</i> , | INFO: Headquarters, Lockheed, | Hycon | |
| | 1. From to mainten | ance personnel. | 25 X 1 |
| | 2. Request identification by serial number when reporting success | | |
| | or difficulty with Drift Sight, Hand | Serial number when reporting a Control or Tracker. Complian | access |
| | will yield increased effectiveness o | f maintenance history. End of | message. |
| | The number of the character may be been also as the character of the character may be a second or the character of the charac | | |
| | The purpose of the above TWX is to permit us better to evaluate the effectiveness of field repairs retrofits and life span of components. | | |
| | • | | |
| | | 1 | |
| | | m | |
| | | | |
| e of | | | |
| | | | 25X1 |
| | TWM: hmm | | 20/(1 |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | trai | |
| | | och " | |
|) | 4/00 = | octroi 56-81-176-0 | ovres |
| Micocol | and bodard | · | |
| Com for it st | a with looking | | |
| man to the first term of the second second | · | | |
| بعر | | | |
| | 5) | | |